Telephone Call / Visit Record / Note to File Industrial Waste Program

King County Di

Department of Natural Resources and Parks Wastewater Treatment Oivision

<u></u>		r=	The state of the s	
Company		Permit/DA No.	Date/Year 15/24/16	
KIL			Time	⊠ a.m. □ p.m.
Contact	Office/Address		Telephone No.	
0	h Mr.		286-796-779t Fax No.	
Porrish Tonggard (PT)	hut		•	
KC Employee			Telephone No.	
Brue Tiffens			Fax No. (206) 263-3001	
☐ Conversation ☐ Left Message ☐ Company Visit			☐ Note to File	
☐ Incoming Call ☐ Meeting				
Subject HCIW STATEMENT SAMPLY & HCIA				
Summary				
I asked PT about SW sampling @ hCT+				
· 6 78 4: It an novacel business brown				
· hegula sumply: 6/6/ti - 1/9/th -> Assume 14 hrs/day				
1 19 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
I color IT about any social bearing after the requirement of				
I asho IT about any special hearing protests requirements of menting that hormal from ear plays are adequate.				
The man in the first the f				
	, and the second		<u> </u>	
Action Required				
, tollow the quite of				
:				
Action Taken				
1465 (Rev. 3/03) •●■1202₩ 🛱			Continue	d on Back

KCSlip4 57016

Tiffany, Bruce

From: Ionsgard, Patricia

Sent: Wednesday, May 24, 2006 11:43 AM

To: Tiffany, Bruce

Subject: RE: King County Industrial Waste Program - Stormwater Sediment Sampling at KCIA

Bruce

The dates and times below will work. Please check in at the airport maintenance shop @ 6518 Ellis Ave. S. I will issue temporary visitor badges at that time.

Patricia Tonsgard

Airfield Maintenance Supervisor

----Original Message----From: Tiffany, Bruce

Sent: Wednesday, May 24, 2006 10:52 AM

To: Tonsgard, Patricia

Cc: Heinz, Dana; Himes, Tammy; Newborn, Greg

Subject: King County Industrial Waste Program - Stormwater Sediment Sampling at KCIA

Hi Patricia;

Here is the map showing the locations of the stormwater vaults we are going to sample. We are also going to sample one catch basin (No. 1741) which is not on this map.

In total, we are planning to sample 8 stormwater vaults and the 1 catch basin for sediment.

We will be conducting the work from Tuesday June 6, 2006 to Thursday June 8, 2006. We will need a KCIA escort from 7:30 a.m. to 4:30 p.m. on those days.

Also, we would like an escort in order to conduct a reconnaissance of all the sample sites on June 1, 2006 between 8:30 and 12:00.

Please let me know if these dates/times are okay and if we need to check with anyone to get security badges.

Thanks,

Bruce

Bruce Tiffany, P.E.
King County - Industrial Waste Program
130 Nickerson St., Suite 200
Seattle, WA 98109-1658
T: 206-263-3011